

Athletic Field Evaluation Form

High/Middle School Upper Left

Field Grade:	1.6
--------------	------------

Date of Evaluation	4/12/2019		
Type of Field:	Multi-Purpose Rectangular (MPR) - Soccer		
Number of Fields:	One (1)		
Typical age of users:			
MPR Field Dimensions:	Length:	Width	Run-Out
	180'	135'	10+'

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry	N/A				
Stand of Turf			X		
Planarity (playing surface - lack of dips, heaves, holes, etc.)		X			
Striping (Completeness, visibility, condition)	N/A				
Fencing (Perimeter fencing, gates, etc.)	N/A				
Irrigation (condition, coverage, reported adequacy)			X		
Safety (Run-outs, lack of obstructions, etc.).		X			
Support Equipment (goals, players benches, etc.)			X		
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)	N/A				
Drainage	N/A				
Average Score = 1.6					

Comments
1. No paved walkways into field, ADA non-compliant. 2. Runout to the south obstructed by storage shed and two wooded posts within 20'. 3. Outdated scoreboard. 4. Outdated on-site storage

Athletic Field Evaluation Form

High/Middle School Upper Left

Field Grade:	2.1
--------------	------------

Date of Evaluation	4/12/2019				
Type of Field:	Softball				
Number of Fields:	One (1)				
Typical age of users:					
Baseball/Softball Dimensions:	1st & 3rd Base	L Field	R Field	C Field	Backstop
	60'	N/A	N/A	N/A	25'

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry / Solar Orientation				X	
Stand of Turf			X		
Infield Condition (Infield material, base paths, etc.)				X	
Planarity (playing surface - lack of dips, heaves, holes, etc.)			X		
Striping (Completeness, visibility, condition)	N/A				
Fencing (Perimeter fencing, backstops, outfield fencing, etc.)			X		
Irrigation (condition, coverage, reported adequacy)			X		
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (bases, dugouts, batting cages, players benches, etc.)		X			
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)		X			
Drainage	N/A				
Average Score =	2.1				

Comments
1. No paved access to field, ADA non-compliant. 2. Infield material notably dense, suggesting poor drainage. 3. Chain link batting cage significantly deformed, interior safety netting loose and torn.

Athletic Field Evaluation Form

High/Middle School Upper Right

Field Grade:	1.9
--------------	------------

Date of Evaluation	4/12/2019		
Type of Field:	Multi-Purpose Rectangular (MPR)-Lacrosse/Field Hockey		
Number of Fields:	One (1)		
Typical age of users:			
MPR Field Dimensions:	Length:	Width	Run-Out
	300'	180'	10+'

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry	N/A				
Stand of Turf			X		
Planarity (playing surface - lack of dips, heaves, holes, etc.)			X		
Striping (Completeness, visibility, condition)	N/A				
Fencing (Perimeter fencing, gates, etc.)		X			
Irrigation (condition, coverage, reported adequacy)			X		
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (goals, players benches, etc.)		X			
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)			X		
Drainage	N/A				
Average Score = 1.9					

Comments
<ol style="list-style-type: none"> 1. Lacking natural turf in front of goals and in center field from overuse. 2. Both soccer and lacrosse goals showing signs of rust and structural damage. 3. No paved access to field, ADA non-compliant. 4. Perimeter fence to the east severely rusted and bent in some areas.

Athletic Field Evaluation Form

High/Middle School Upper Right

Field Grade:	2.0
--------------	------------

Date of Evaluation	4/12/2019				
Type of Field:	Softball				
Number of Fields:	One (1)				
Typical age of users:					
Baseball/Softball Dimensions:	1st & 3rd Base	L Field	R Field	C Field	Backstop
	60'	N/A	N/A	N/A	

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry / Solar Orientation			X		
Stand of Turf			X		
Infield Condition (Infield material, base paths, etc.)			X		
Planarity (playing surface - lack of dips, heaves, holes, etc.)		X			
Striping (Completeness, visibility, condition)	N/A				
Fencing (Perimeter fencing, backstops, outfield fencing, etc.)			X		
Irrigation (condition, coverage, reported adequacy)			X		
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (bases, dugouts, batting cages, players benches, etc.)		X			
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)				X	
Drainage	N/A				
Average Score =	2.0				

Comments
<ol style="list-style-type: none"> 1. Paved access to field is significantly sloped, ADA non-compliant. 2. Backstop and fencing around dugouts damaged and rusting in some areas. 3. Infield material overly dense, suggesting poor drainage. 4. Edges of infield becoming overgrown.

Athletic Field Evaluation Form

High/Middle School Field Turf Baseball

Field Grade:	3.3
--------------	------------

Date of Evaluation	4/12/2019				
Type of Field:	Baseball				
Number of Fields:	One (1)				
Typical age of users:					
Baseball/Softball Dimensions:	1st & 3rd Base	L Field	R Field	C Field	Backstop
	60/90'	N/A	N/A	N/A	25'

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry / Solar Orientation			X		
Stand of Turf					X
Infield Condition (Infield material, base paths, etc.)					X
Planarity (playing surface - lack of dips, heaves, holes, etc.)					X
Striping (Completeness, visibility, condition)					X
Fencing (Perimeter fencing, backstops, outfield fencing, etc.)				X	
Irrigation (condition, coverage, reported adequacy)	N/A				
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (bases, dugouts, batting cages, players benches, etc.)				X	
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)					X
Site Lighting				X	
Spectator Seating (condition, size, accessibility, etc.)			X		
Drainage	N/A				
Average Score =	3.3				

Comments
<ol style="list-style-type: none"> 1. Paved entryway into field, ADA compliant. Only two accessible parking spots in lot adjacent to field. 2. Orientation may leave batters affected by late afternoon sun. 3. Dugouts set back from fence line and well protected. 4. Spectator seating parallel to the first base line is unsafely exposed to foul balls. 5. Both foul poles leave little to no run out.

Athletic Field Evaluation Form

High/Middle School Synthetic Turf MPR

Field Grade:	3.4
--------------	------------

Date of Evaluation	4/12/2019		
Type of Field:	Multi-Purpose Rectangular (MPR)		
Number of Fields:	One (1)		
Typical age of users:			
MPR Field Dimensions:	Length:	Width	Run-Out
	330/360	180/160	

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry					X
Stand of Turf					X
Planarity (playing surface - lack of dips, heaves, holes, etc.)					X
Striping (Completeness, visibility, condition)					X
Fencing (Perimeter fencing, gates, etc.)					X
Irrigation (condition, coverage, reported adequacy)	N/A				
Safety (Run-outs, lack of obstructions, etc.).			X		
Support Equipment (goals, players benches, etc.)				X	
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)					X
Site Lighting				X	
Spectator Seating (condition, size, accessibility, etc.)			X		
Drainage	N/A				
Average Score = 3.4					

Comments
1. Paved entryway into field, ADA compliant. Only two accessible parking spots in lot adjacent to field. 2. Run out from both northeast and southeast corners is 6' or less to either a fence or retaining wall.

Athletic Field Evaluation Form

West Street Athletic Field Complex

Field Grade:	1.8
--------------	------------

Date of Evaluation	4/12/2019		
Type of Field:	Multi-Purpose Rectangular (MPR) - Soccer		
Number of Fields:	One (1)		
Typical age of users:			
MPR Field Dimensions:	Length:	Width	Run-Out
	270'	180'	

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry				X	
Stand of Turf		X			
Planarity (playing surface - lack of dips, heaves, holes, etc.)		X			
Striping (Completeness, visibility, condition)			X		
Fencing (Perimeter fencing, gates, etc.)	N/A				
Irrigation (condition, coverage, reported adequacy)		X			
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (goals, players benches, etc.)		X			
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)			X		
Drainage	N/A				
Average Score = 1.8					

Comments
<ol style="list-style-type: none"> 1. No paved walkways provided into field, ADA non-compliant. 2. Spectator seating consists of only two picnic tables. 3. Surface loose and lacking natural turf from heavy use in center field and near both goals. 4. Netting loose or torn on both goals. 5. No on-site storage.

Athletic Field Evaluation Form

West Street Athletic Field Complex

Field Grade:	1.7
--------------	------------

Date of Evaluation	4/12/2019		
Type of Field:	Multi-Purpose Rectangular (MPR) - Soccer		
Number of Fields:	One (1)		
Typical age of users:			
MPR Field Dimensions:	Length:	Width	Run-Out
	170'	110'	

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry				X	
Stand of Turf		X			
Planarity (playing surface - lack of dips, heaves, holes, etc.)		X			
Striping (Completeness, visibility, condition)			X		
Fencing (Perimeter fencing, gates, etc.)	N/A				
Irrigation (condition, coverage, reported adequacy)		X			
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (goals, players benches, etc.)		X			
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)	N/A				
Drainage	N/A				
Average Score = 1.7					

Comments
1. No paved walkways provided into field, ADA non-compliant. 2. Relatively planar surface, lacking natural turf near both goals. 3. No apparent spectator seating. 4. No on-site storage. 5. Lacking natural turf near both goals.

Athletic Field Evaluation Form

West Street Athletic Field Complex

Field Grade:	1.7
--------------	------------

Date of Evaluation	4/12/2019		
Type of Field:	Multi-Purpose Rectangular (MPR) - Soccer		
Number of Fields:	One (1)		
Typical age of users:			
MPR Field Dimensions:	Length:	Width	Run-Out
	170'	110'	

	N/A	Poor (1)	Fair (2)	Good (3)	Excellent (4)
Geometry				X	
Stand of Turf		X			
Planarity (playing surface - lack of dips, heaves, holes, etc.)		X			
Striping (Completeness, visibility, condition)			X		
Fencing (Perimeter fencing, gates, etc.)	N/A				
Irrigation (condition, coverage, reported adequacy)		X			
Safety (Run-outs, lack of obstructions, etc.).				X	
Support Equipment (goals, players benches, etc.)		X			
Athletic Lighting (reported adequacy, lack of spill / glare, general condition, etc.)	N/A				
Site Lighting	N/A				
Spectator Seating (condition, size, accessibility, etc.)	N/A				
Drainage	N/A				
Average Score = 1.7					

Comments
1. No paved walkways into field, ADA non-compliant. 2. Lacking natural turf near both goals. 3. No apparent spectator seating. 4. Both goals are in poor condition. 5. No on-site storage.

High School / Middle School – Turf MPR Field



Paved access to field, ADA compliant.



Trench drain in concrete transition at primary access entryway.



Minimal run out before fence in north-east corner of field.



Spectator seating at the south-east corner of the field.

High School / Middle School – Turf Baseball Field



Foul pole in right field does not leave any run out.



Spectator seating to the right of the first base line is exposed to foul balls.



Well protected dugout seating along first base line.



Spectator seating and scoreboard along third base line.

High School / Middle School – Softball Field No. 1



No paved access to field, ADA non-compliant.



Chain link batting cage showing structural damage and loose protective netting.



Infield material notably dense in some areas, particularly around home plate.



Sole spectator seating along third base line.

High School / Middle School – MPR Field No. 1



Run out at the south end of the field obstructed by shed and wooden posts within 20 feet of goal.



Outdated scoreboard.



Outdated on-site storage.



No paved access to field, ADA non-compliant.

High School / Middle School – Softball Field No. 2



Paved access to field is significantly sloped, ADA non-compliant.



Backstop fencing damaged and showing signs of rust.



Edges of infield becoming less defined and slightly overgrown.



Spectator seating parallel to third base line.

High School / Middle School – MPR Field No. 2



Goal on southern end of field showing damage to supports and netting.



Gravel drive in south-east corner. No paved access to field, ADA non-compliant.



Lacrosse goal with signs of rust. Surrounding area lacking sufficient grass cover.



Perimeter fence damaged and overgrown.

West Street Athletic Fields – Field No. 1



No paved access to fields, ADA non-compliant.



Gravel parking area.



Soccer goals on western side of field.



Loose soil and worn natural turf in center of playing field.

West Street Athletic Fields – Fields No. 2 & 3



Soccer goal with damaged natural turf on southern side of field no. 2.



Rear side of wooden practice area adjacent to field no. 2.



Damaged goal and lack of natural turf on northern side of field no. 3.



Outdated spectator seating in rear of field no. 3.